

Edison Memorial Tower Restoration Update:



Before any work took place, the contractor carefully labeled and removed all of the large stones on the plaza level surrounding the tower base in order to ensure that the weight of the scaffolding did not hurt the stones. In addition, the engraved pavers that are located within the construction fence were protected with rubber matting. Once these protections were in place, the scaffolding started rising!



The project team meets weekly to coordinate their efforts, report on work to date, and discuss any current issues.



As an example of the type of exploratory investigation that is necessary, the construction team opened up a patch of the tower in order to measure the depth of the exterior layer of concrete.



37 Christie Street
Edison, NJ 08820

Thomas Edison Center
at Menlo Park

June 22, 2011